

General Environmental Incident Summary

Incident: 3231 **Date/Time Notice:** 3/6/2014 2145 **DEM Incident No:**

Responsible Party: North Dakota Pipeline Company LLC (dba NDPL LLC)

Date Incident: 3/6/2014 **Time Incident:** 2010 **Duration:**

County: Williams **Twp:** 154 **Rng:** 102 **Sec:** 34 **Qtr:** SE SE

Lat: 48.11215 **Long:** -103.77820 **Method:** Navigation quality GPS

Location Description: Trenton Station - 4807 Hwy 1804, Trenton, ND 58853

Submitted By: Valerie Lavik

Affiliation: Compliance Coordinator

Address: 2505 16th St SW

City: Minot

State: ND

Zip: 58701

Received By:

Contact Person: Kevin Gault
2505 16th St. SW
Minot, ND 58701

Distance Nearest Occupied Building: 5 Miles

Release Contained: Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 3.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Seal failed on a pump

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Contaminated soil will be removed and hauled to an approved disposal facility.

Action Taken or Planned:

Release is contained within station manifold dike.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 3/9/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release at pipeline station. Followup is necessary.

Date: 3/19/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location at 13:45, 3/19/14. 40 degrees F, sunny, NW wind 5-15 mph. Spoke with the electrician for Enbridge who guided me to the release location. Observed the site and took photos. The release had occurred because of a failed seal on a pump assembly that sat upon a concrete lift. The release sprayed out and impacted an area around the concrete lift in an approximate area of 30 feet by 50 feet inside of the containment berm.

The area showed signs of soil removal from the impact area. No hydrocarbon odors were detected during a scent test of the area soils, except for in a small area west of the concrete pad, under the staircase.

Phoned supervisor and awaiting return call to determine full extent of soil removal.

Date: 9/15/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location at 8:00. 56 degrees F, Mostly cloudy, NW wind 15-25 mph. Unable to enter facility due to fencing and gate being locked. However, due to the close proximity of the release area and the fencing, I was able to visually observe the area of concern. The area of concern did not show any visible petroleum staining as documented from the last inspection. Photos of the area were taken. No further followup needed at this time.